


Field of education:
Mechanical engineering

Professional qualification:
CNC operator

Exercise:
**Programming of CNC machine
(solution)**

Variant:
Task 58 – Sprocket 5.1.

Solution:




Required written code that should be inserted into the control unit:

```
G0 Z5  
X18,14 Y59,254  
G1 Z-2  
G2 Y90,746 R59  
G1 X37,125 Y87,398  
X45,325 Y101,602  
X32,934 Y116,369  
G2 X60,206 Y132,115 R59  
G1 X66,8 Y114  
X83,2  
X89,794 Y132,115  
G2 X117,066 Y116,369 R59  
G1 X104,675 Y101,602  
Z5  
M30
```

Explanation of the G-code:

```
%Setting the coordinate system x=0, y=0, z=0; point 0  
G0 Z5 %Lifting of tool; point 1  
X18,14 Y59,254 %Positioning at the starting point; point 2  
G1 Z-2 %Tool entry into material; point 3  
G2 Y90,746 R59 %Radial milling; point 4  
G1 X37,125 Y87,398 %Straight milling; point 5  
X45,325 Y101,602 %Straight milling; point 6  
X32,934 Y116,369 %Straight milling; point 7  
G2 X60,206 Y132,115 R59 %Radial milling; point 8  
G1 X66,8 Y114 %Straight milling; point 9  
X83,2 %Straight milling; point 10  
X89,794 Y132,115 %Straight milling; point 11  
G2 X117,066 Y116,369 R59 %Radial milling; point 12
```



G1 X104,675 Y101,602 %Straight milling; point 13

Z5 %Lifting of tool; point 14

M30 %End of program