



Co-funded by the  
Erasmus+ Programme  
of the European Union



Erasmus+

# MODULE R

## Safety in resistance welding

Danger of burns



## Protection against burning

- ▶ Must be checked before starting work preventively remove all flammable materials.
- ▶ This It is important for prevention of fire or explosion.
- ▶ Before burn protects the welder personal protective equipment such as leather apron, leather gloves, prescribed work clothing, work shoes prescribed, respectively cap.
- ▶ Eyes a worker protecting glasses or shield of plexiglass.