

Co-funded by the Erasmus+ Programme of the European Union





MODULE R Safety in resistance welding

Personal protective equipment for resistance welding worker

Erasmus+

2

Personal protective equipment for resistance welding worker

- The basic safety equipment includes prescribed work clothing, boots, gloves and apron.
- To eye protection is required goggles fitted with dark glasses or use a protective shield, which is made of organic glass.



3

Spot welder

