



Co-funded by the
Erasmus+ Programme
of the European Union



Erasmus+

MODULE R

Safety in resistance welding

The heat released by radiation



The heat released by radiation

- Against heat welder to protect the personal protective equipment.
- Worker yet secure workstation screens, covers, curtains, drapes, to endanger themselves or other personnel with spray welding spark, or molten metal.